

0 HD 980611065

M E M O

DATE: January 23, 1984  
TO: FILE  
FROM: Scott Byram *SB*  
SUBJECT: Fram Property Dump (The Mogul Corp.)  
Chagrin Falls, OH. OHD980611065

US EPA RECORDS CENTER REGION 5



492576

The reason that a hazard ranking has not been included with the site inspection form for this site, is that no useful information on waste characteristics could be gathered by the inspection team during their visit. Interviews (either in person or by telephone) of State (OEPA), and City employees, the current owner, the Mogul Corp., and Mr. Fram's son have been fruitless. It was evident during the inspection that sampling of surface water or soils would have yielded no additional useful information. In order to obtain waste information for this site, it maybe necessary to auger through the fill with a drill rig and take soil snaples at various depths.

Unfortunately until more waste characteristics information becomes available the site HRS score has to be zero.

SB

*Sample nearby well  
Possibly install well next to dump or downgradient  
from the dump*

## M E M O

DATE: January 23, 1984  
TO: FILE  
FROM: Scott Byram ~~SB~~  
SUBJECT: Fram Property Dump (The Mogul Corp.)  
Chagrin Falls, OH. OHD980611065 #328

The reason that a hazard ranking has not been included with the site inspection form for this site, is that no useful information on waste characteristics could be gathered by the inspection team during their visit. Interviews (either in person or by telephone) of State (OEPA), and City employees, the current owner, the Mogul Corp., and Mr. Fram's son have been fruitless. It was evident during the inspection that sampling of surface water or soils would have yielded no additional useful information. In order to obtain waste information for this site, it maybe necessary to auger through the fill with a drill rig and take soil samples at various depths.

Unfortunately until more waste characteristics information becomes available the site HRS score has to be zero.

SB